

COUNCIL COMMUNICATION

TO :

City Council

FROM:

City Kanager

MEETING DATE:

February 17, 1988

AGENDA TITLE:

Traffic Studies - Discussion and Appropriate Action

a) Establish "No Parking" Zone on North Side of Tokay Street West of Ham Lane

b) Donner Drive/Calaveras Street and Pioneer Drive/Calaveras Street, Intersection Control

Correct Traffic Resolution, Miscellaneous Locations

RECOMMENDED ACTION: That the City Council discuss the individual items listed below and adopt appropriate resolutions.

Iten

Recommended Action

a) Establish "No Parking" Zone on North Side of Tokay Street West of Ham Lane Adopt resolution - see attached memo

b) Donner Drive/Calaveras Street and Pioneer Drive/Calaveras Street, Intersection Control Adopt resolution amending the Traffic Resolution per attached memo

c) Correct Traffic Resolution, Miscellaneous Locations Adopt resolution amending the Traffic Resolution as follows:

Section 2-C-2, Two-Way and One-Way Stop Intersections

 Woodhaven Lane (Southbound) stops at Eilers Lane - Add

Section 2-D, Yield Intersections

Main Street yields at Locust
Street - Add

Mariposa Way yields at Cross Street - kdd

 Murray Street yields at Calaveras Street - Add

Ravenwood Way yields at Coventry Way - Add

 Ridge Drive yields at Aspen Grove Drive - Add

APPROVED:

This. a. Silvison

FILE NO.

THOMAS A. PETERSON, City Manager

City Council Traffic Studies February 17, 1988 Page 2

Item

c) Correct Traffic Resolution, Miscellaneous Locations (Cantinued)

Recommended Action

Adopt resolution amending the Traff c Resolution as follows:

° Turner Road (right turn eastbound yields at Lower Sacramento Road/ Woodhaven Lane - Add

Section 7, Speed Limits Harney Lane, West City Limit to East City Limit, 45 MPH - Add

Woodhaven Lane, Turner Road to Eilers Lane, 35 MPH - Revise to 30 MPH

BACKGROUND INFORMATION:

Separate memos discussing Items a) and b) are attached. Item c) consists of corrections to reflect existing conditions that were overlooked when the Traffic Resolution was adopted in December 1987.

Jack . Ronsko

Public Works Director

JLR/RCP/ma

Attachments

Assistant Civil Engineer Street Superintendent

Police Chief

T0:

City Council

FROM:

City Manager

MEETING DATE:

February 17, 1988

AGENDA TITLE:

a) Establish "No Parking" Zone on North Side of Tokay Street

West of Ham Lane

RECOMMENDED ACTION: That the City Council establish a 210' no parking zone on the north side of Tokay Street west of Ham Lane. (See attached plan.)

BACKGROUND INFORMATIOM: At the February 3, 1988 City Council meeting, City Council reviewed a request from Chuck Wentland concerning the sight problem at the Ham Lane Professional Center. (See attached Council Communication.) City Council approved the no parking zone on Ham Lane and requested that staff contact the Bank of Lodi regarding the recommended no parking zone on Tokay Street.

Staff contacted David Vietmeier, the Vice President and Cashier of Bank of Lodi and he does not have any objections to the no parking zone on the north side of Tokay Street west of Ham Lane.

Currently, the Bank of Lodi is reviewing parking alternatives to help alleviate the parking problems on Tokay Street. One of 2...ose alternatives is use of a church parking lot located across the street from the bank. The Bank of Lodi is also planning to install additional parking spaces with the expansion of the bank in the near future.

Staff recommends installing the 210' no parking zone on the north side of Tokay Street from Ham Lane to the Ham Lane Professional Center driveway, and the 15' no parking zone west of the fire hydrant located west of the driveway.

Jack\L. Ronsko

Public Works Director

JLR/PJF/cag

Attachments

cc: Street Superintendent

Police Chief

Dave Vietmeier, Vice-president & Cashier, Bank of Lodi

Chuck Wentland, Ham Lane Professional Center


APPROVED:

THOMAS A. PETERSON, City Manager

FILE NO.

CCNPTOKY/TXTW.01C

February 9, 1988



+b:

City Council

FROM:

City Manager

MEETING DATE:

February 3, 1968

AGENDA TITLE:

Establish No Parking Zone on Tokay Street West of Ham Lane

and Ham Lane South of Lodi Avenue

RECOMMENDED ACTION: That the City Council establish a 210' no parking zone on the north side of Tokay Street west of Ham Lane and a 40' no parking zone on the west side of Ham Lane south of the northern Ham Lane Professional Center driveway. (See attached plan.)

BACKGROUND INFORMATION: Chuck Wentland sent the attached letter requesting staff to review the sight problem at the Hm Lane Professional Center driveways (Tokay Street driveway and the northern Ham Lane driveway). Staff made a number of field observations and witnessed sight problems at both ariveways.

On Tokay Street, the combination of the parked vehicles and the street curvature cause a sight problem for motorists exiting the driveway. The majority of the parked vehicles (approximately 10 spaces) are employees of the Bank of Lodi. It appears the employees are parking their vehicles on-street, allowing their customers use of the parking lot (approximately 30 spaces). During our observations, the Bank of Lodi parking lot was half full. By removing the 10± spaces on Tokay Street, those vehicles parking in the area may move west to the residential area. Staff cannot force employers to allow employee parking in their parking lot. Similar situations have occurred in many parts of Lodi. The result is unhappy neighbors, reduced traffic safety, and controversial Council decisions. The City Council and Planning Commission should consider revising the parking standards to avoid these types of situations.

We recommend installing the 210' no parking zone on the north side of Tokay Street from Ham Lane to the Ham Lane Professional Center driveway. Staff also recommends installing a 15' no parking zone west of the fire hydrant located west of the driveway. Because of the fire hydrant, this can be done without specific Council action. Staff observed vehicles parking within 15' of the fire hydrant, and installing the no parking zone will improve the sight problem.

APPROVED:

THOMAS A. PETERSON, City Manager

FILE NO.

CNOPAR12/TXTW.02M

January 27, 1988

City Council No Parking Zone February 3, 1988 Page 2

On Ham Lane, staff frequently witnessed a vehicle parked south of the northern driveway. Installing the 40' no parking zone will improve the sight problem at this location. This will not cause an inconvenience for motorists using this area other than moving them south.

ďack\L. Ronsko

Publia Works Director

SLR/PJF/ma

Attachments

Street Superintendent Police Chief C.A. Wentland, Ham Lane Professional Center


Bank of Lodi

Ham Lane Professional Center, A California Corporation

TELEPHONE (209) 333-0900 • 301 SOUTH HAM LANE, SUITE A • LCDL CALIFORNIA 95242

December 18, 1987

Mr. Jack Ronsko Public Works Director City of Lodi Lodi, CA. 95240



Dear Mr. Ronsko:

May I respectfully request that you visit our complex and investigate the possibility of providing some red curb near the driveways to allow the vehicle driver the ability to see roadway traffic on Ham Lane and Tokay Streets when they are making a movement onto those streets.

The driveway that seems to have the most traffic is that one on Ham Lane, west of Lodi Avenue. When a vehicle is parked immediately south of that driveway, it is extremely difficult to see Ham Lane traffic heading north. Of course yon probably don't have any trouble because of your size, but there are a Lot of elderly people, who hold valid drivers licenses that do not see much above the vehicle dash board and have difficulty seeing the cross traffic because of vehicles parked at the curb.

I have noticed problems also with the westly flow of traffic at Tokay Street driveway. I have Listened to your reasoning with the City Council on why you recommend this or that over the years and believe I understand your philosophy on intersection control (although I 'nave not been privileged to receive that communication as the Council has), but I do not know your personal concept as to egress and curb markings on the subject of this Letter. I do know that the northern Ham driveway gets a lot of traffic and feel that a red curb of say 50 feet or more to the south of that exit would be worthwhile.

There is attached a plot plan of the area, I have marked in yellow the areas that I believe should be examined.


Awaiting your visit, I remain

C. A. Wentland

Very truly yours

THE REPRODUCTION OF THIS
DOCUMENT CANNOT BE
IMPROVED DUE TO THE

Please Note: This plot plan is t accurate as to the location of the driveways, nor the buildings. We have experienced no problem on the Lodi





COUNCIL COMMUNICATION

TO:

City Council

FROH:

City Manager

MEETING DATE:

February 17, 1988

AGENDA TITLE:

b) Donner Drive/Calaveras Street and Pioneer Drive/Calaveras

Street, Intersection Control

<u>RECOMMENDED ACTION</u>: That the City Council approve the installation of yield signs on Donner Drive at Calaveras Street and on Calaveras Street at Pioneer Drive.

BACKGROUND INFORMATION: At the January 6, 1988 City Council meeting, the residents in the vicinity of Lawrence School requested stop signs be installed at the Donner Drive/Calaveras Street and Pioneer Drive/Calaveras Street intersections (see attached petition). The City Council directed staff to evaluate the two intersections and bring the results to the City Council as soon as possible.

Staff performed the cecessary studies. Daily traffic counts were taken and accident records were reviewed. There have been no accidents at Pioneer Drive/Calaveras Street in the past four years. At the Donner Drive/Calaveras Street intersection, there have been no accidents in 1984, 1985 and 1986, and one right-angle accident in 1987. The primary collision factor was the eastbound motorist failed to yield to the northbound motorist.

Both intersections are "T" intersections and have no controls.

The State of California multi-way stop sign guidelines were used to evaluate the need for multi-way stop signs. Based on the traffic counts and accident records, multi-way stop signs are not justified at these intersections (see attached warrants).

Staff then reviewed the need for a yield or stop sign on the minor street. The City uses its own intersection control guidelines for three-way intersections. If the major street has an approximate traffic volume of 2000 vehicles per day, the minor street should be controlled. A stop or yield sign is used depending on various factors: volumes, sight distance, accidents, etc.

APPROVED:

Thos. a. Siercon

FILE NO.

THOMAS A. PETERSON, City Manager

CDONNER/TXTW.02M

February **10**, 1988

City Council Donner/Calaveras February 17, 1988 Page 2

Based on these guidelines, yield signs are justified on Donner Drive at Calaveras Street and on Calaveras Street at Pioneer Drive.

4800

Tack J. Ronsko Public Works Director

JLR/PJF/ma

Attachments

Street Superintendent cc:

Police Chief Deborah Myers Cheri Gribayedoff

Lawrence School Principal, Ed McCaughna

This is to fetition rotop summanate the intersections of Donner Calaveras Servet. Below are estimated concerned for the Europe of thildren) in the Lawrence School and and the increasing number of modulators of the speed law.

1. abeborah Thyro Eco Calaucias

2. Cheri The bayett 77 72 Calaucias

3. Survey Le Bayett 77 721 Calaucias Street, Locke Ca.

5. Beverly J. Hong 721 Calaucias Street, Locke

6. Beverly J. Hong 721 Calaucias Street, Locke

7. Janine Barton 721 Calaucias St. Joshi

8. Kin Janilla 513 Cilcanian St. Locke

9. Vine Clay 513 Cilcanian St. Locke

10. Janilla 513 Cilcanian St. Fode

11. Janilla 513 Cilcanian St. Fode

12. Mana L. Canantis 946 Hoppy et. July 49. 98. 2.

13. Nancy Cadent 50 West Laust #7 Loth, A. 95246

14. Ferrantee 14626 E Cican, trampoli 95320

15. Sennett L. Chamber 3255 Beauty Stan 9520

16. Carolyne Shapilla 3255 Beauty Stan 9520

THE REPRODUCTION OF THIS DOCUMENT CANNOT BE IMPROVED DUE TO THE CONDITION OF THE ORIGINAL



low volume intersections.

MULTI-WAY STOP SIGN WARRANTS

INTERSECTION OF DONNER and CALAVERAS ST DATE 2-1-88 Any of the following conditions may warrant a multi-way STOP sign installation. Where traffic signals are warranted and the need is urgent, the four-way stop is an interim measure that can be installed quickly to control traffic while arrangements are being made for the signal installation, Satisfied~-Not Satisfied V An accident problem, as indicated by five or more reported accidents of a type susceptible of correction by a multi-way stop installation in a 12-month period. Types of accidents susceptible of correction include right angle and left turn collisions. Time period JAN-DEC 1987 Number of correctible accidents Total number of accidents_____ Satisfied Not Satisfied Minimum volume warrant: The total vehicular volume entering the intersection from al7 approaches must average at least 500 vehicles per hour for any eight hours of an average day, and Highest 8 hours 7 a.m. to _5 p.m. Total volume 179 vehicles

Average per hour 147 vehicles Major Street |107 | 94 | 90 | 143 | 132 | 100 | 83 | 87 Minor Street 62 28 22 42 40 70 33 46 Not Satisfied Satisfied The combined vehicular and pedestrian volume from the minor street or highway must average at least 200 units per hour for the same eight hours with an average delay to minor street vehicular traffic of at least 30 seconds per vehicle during the maximum hour, and Pedestrians 230 | 210 | 330 ≈10 Satisfied Not Satisfied SUBGESTED ROUTE TO SCHOOL- STUDENTS CROSS When the 85-percentile approach speed of the major street traffic exceeds 40 miles per hour, the minimum vehicular volume warrant is 70 percent of the above requirements. 85-percentile speed 27 MPH(est.)
Satisfied Not Satisfied A four-way STOP sign installation is a useful traffic control measure when other available means of control are not adequate. It should not be used unless the volume of traffic on the intersecting roads is about equal and is undesirable at

Traffic major street 14
Traffic minor street 26



CITY OF LODI

PUBLIC WORKS DEPARTMENT

MULTI-WAY STOP SIGN WARRANTS


INTERSECTION OF PIONEER DR. and CALAVERAS ST DATE 2-3-88 BY PJF	
Any of the following conditions may warrant a multi-way STOP sign installation.	
i. Where traffic signals are warranted and the need is urgent, the four-way sto is an interim measure that can be installed quickly to control traffic while arrangements are being made for the signal installation.	
Satisfied Not Satisfied	<u> </u>
2. An accident problem, as indicated by five or more reported accidents of a ty susceptible of correction by a multi-way stop installation in a 12-month period. Types of accidents susceptible of correction include right angle at left turn collisions.	-
Time period JAN-DEC 1987 Number of correctible accidents E Satisfied Not Sat isfied)
3. Minimum volume warrant:	
a, The total vehicular volume entering the intersection from a71 approache must average at least 500 vehicles per hour for any eight hours of an average day, and	
Hour 10 10 W W W W W W W W W	o.m.
b. The combined vehicular and pedestrian volume from the minor street or highway must average at least 200 units per hour for the same eight hou with an average delay to minor street vehicular traffic of at least 30 seconds per vehicle during the maximum hour, and	rs
Hour A A A A A A A A A A A A A A A A A A A	(EST)
c. When the 85-percentile approach speed of the major street traffic excee miles per hour, the minimum vehicular volume warrant is 70 percent of the above requirements.	ds 40 ne
85-percentile speed 27 MPH(est.) Satisfied Not Satisfied	
A four-way STOP sign installation is a useful traffic control measure when othe available means of control are not adequate. It should not be used unless the volume of traffic on the intersecting roads is about equal and is undesirable a low volume intersections.	
% Traffic major street 69 % % Traffic minor street 31 %	



CITY OF LODI

PUBLIC WORKS DEPARTMENT

INTERSECTION CONTROL STUDY



RESOLUTION NO. 88-22

RESOLUTION ESTABLISHING A "NO PARKING" ZONE ON THE NORTH SIDE OF TOKAY STREET WEST OF HAM LANE

RESOLVED, that the City Council of the City of Lodi does hereby establish a 210 foot "No Parking" zone on the north side of Tokay Street west of Ham Lane as shown on Exhibit "A" attached hereto and thereby made a part hereof.

Dated: February 17, 1988

I hereby certify that Resolution No. 88-22 was passed and adopted by the City Council of the City of Lodi in a regular meeting held February 17, 1988 by the following vote:

Ayes: Council Members - Hinchman, Pinkerton, Reid and Snider

Noes: Council Members - None

Absent: Council Members - Olson

Wite In Bisniche Alice M. Reimche City Clerk

RUNTINGTON DR. ST. TOKAY RESIDENCE HAH HAM LH. PROFESSIONAL CENTER FIRE HYDRANT THICKALL SIO, HO LYKKING INSTALL IS' NO PARKING RESIDENTIAL AREA LODI AVE. EANK OF LOD! RESIDENTIAL APEA MAH LH. THETALL 40' NO PARKING EXISTING NO PARKING 7 (CITY COUNCIL APPROVED ON 2-3-86) IWI LN. PROFESSIONAL CENTER LOD AVE. FROFESSIONAL CENTER CITY OF LODI Approved 87 TOKAY ST / HAM LN 1/88 " R.S.K. NO FARKING ZONES

RESOLUTION NO. 88-23

RESOLUTION APPROVING THE INSTALLATION OF "YIELD" SIGNS ON OGNKER DRIVE AT CALAVERAS STREET AND ON CALAVERAS STREET AT PIONEER DRIVE

RESOLVED, THAT THE City Council of the City of Lodi does hereby establish "Yield" signs on Donner Drive at Calaveras Street and on Cdlaveras Street at Pioneer Drive as shown on Exhibit "A" attached hereto and thereby made a part hereof.

Dated: February 17, 1988

I hereby certify that Resolution No. 88-23 was passed and adopted by the City Council of the City of Lodi in a regular meeting held February 17, 1988 by the following vote:

Ayes: Council Members - Pinkerton, Reid and Snider

Nces: Council Members - Hinchman

Absent: Council Members - Olson


Ultice In Picinica Alice M. Reimche City Clerk



CITY OF LODI

PUBLIC WORKS DEPARTMENT

INTERSECTION CONTROL STUDY



RESOLUTION NO. 83-24

RESOLUTION AMENDING RESOLUTION NO. 87-163 ENTITLED "TRAFFIC RESOLUTION"

RESOLVED, that %heCity Council of the City of Lodi dces hereby approve the following amendments to Resolution No. 87-163:

1. That Section 2-C-2, entitled "Two-Way and One-Way Stop Intersections", be revised by adding the following:

"Woodhaven Lane (southbound) stops at Ei ers Lane"

2. That Section 2-D, entitled "Yield Intersect ons", be revised by adding the following:

"Main Street yields at Locust Street
Mariposa Way yields at Cross Street
Murray Street yields at Calaveras Street
Ravenwood Way yields at Coventry Way
Ridge Drive yields at Aspen Grove
Turner Road (right turn eastbound) yields at tower Sacramento Road/
Woodhaven Lane"

3. That Section 7, entitled "Speed Limits", be revised by adding the following:

"Harney Lane, West City Limit to East City Limit, 45 MPH"

4. That Section 7, entitled "Speed Limits", be revised by changing the speed limit on Woodhaven Lane, from Turner Road to Eilers Lane, from 35 MPH to 30 MPH.

Dated: February 17, 1988

I hereby certify that Resolution No. 88-24 was passed and adopted by the City Council of the City of Lodi in a regular meeting held February 17, 1988, by the following vote:

Ayes: Councilmembers - Hinchman, Pinkerton, Reid, and Snider

Noes: Councilmembers - None

Absent: Councilmembers - 01 son (Mayor)

City Clerk